

Masto Wireservice AS

Fra: Shaune Stubbs <Shaune.Stubbs@boa.no>
Sendt: 15. januar 2019 12:33
Til: Masto Wireservice AS
Emne: Supply of 103mm Seals (Actual size measured 104-105mm)
Vedlegg: 20181209_093323.jpg; 20181209_094027.jpg; 20181209_091926.jpg

Good afternoon Tor,

And Happy New Year,

After several years operating in Nigeria the vessels will be coming home to Europe.

Please could you forward a quotation and lead time for four sets of 103mm seals (Actual size measured 104-105mm) These will be needed quite urgently by the end of the month if possible and delivered to my home address in the UK.

I have attached a couple of photos of a 103mm wire installed in 2011 and cut-back for re-termination in December. The wire had not been lubricated in over a year the surface had superficial corrosion.

However, the wire was previously lubricated annually, and obviously penetrated the outer/inner layers as plenty of lubrication was present, with no indications of wire wear. So, the system definitely works!

Hear from you soon,

Kindest regards



Shaune Stubbs
Lifting Equipment Inspector
+4773991199 | Direct
+44 (0)7951443160 | Cell
Shaune.Stubbs@boa.no | www.boa.no

Boa Management AS
Strandveien 43
N-7067 Trondheim

NOTICE: This email contains information that is confidential, proprietary, privileged, or otherwise legally protected from disclosure. If you are not the named addressee, you are not authorized to read, print, retain, copy, or disseminate this email or any part of it. If you received this email in error, please immediately notify the sender by reply email, and delete all copies of this email and any attachments.